


LOADING CHART

Envelope Temperature: 110°C



If 110°C load chart is selected Pasha Balloons highly recommend smooth maneuvering and the use of an electronic envelope temperature sensor. As Pasha Balloons AFM indicates, 120°C must not be exceeded in any circumstances.